

S-TEX 581

CARE INSTRUCTION

- Protection against mechanical risks.
- Do not use where there are chemical, electrical, thermal or entanglement risks.
- The performance levels apply to the coated surface only.
- Designed to enhance fit, the length of gloves may not conform to EN 420 standard.
- Store in a dry place, away from the light.
- Wash at 40°C max.
- No change in performance after 3 wash cycles.
- Cut resistance according to ISO 13997 31N for new unused, 30N after washing.

MATERIAL

Liner: Nylon, Polyester, Aramid, Stainless steel, Other

Coating: Nitrile

COUNTRY OF ORIGIN

Vietnam

STANDARDS



EC Type Examination Certificate From SGS United Kingdom Ltd., 202B Worle Parkway, Weston-super-Mare, BS22 6WA, UK Notified Body No.0120

EN 420:2003+A1:2009 Dexterity

Level 5 (Min.1 - Max.5)

EN 388:2003



 Mechanical risks

 Abrasion (Min.0 - Max.4)
 4

 Cut (Min.0 - Max.5)
 5

 Tear (Min.0 - Max.4)
 4

 Puncture (Min.0 - Max.4)
 2

PACKAGING

1 pair in a bag 120 pairs in a carton

SIZE

6/S 7/M 8/L 9/XL 10/XXL

SHOWA GLOVE Co. 565 TOHORI, HIMEJI HYOGO 670-0802 JAPAN www.showaglove.co.jp/asia

